

Tripstop, being made from PVC is easily cut to length. Tripstop can easily be cut by hand in the field using a sharp fine tooth saw such as a panel saw - 10 teeth to the inch or more. A hack saw with a course cut is also suitable.

Tripstop may be also cut with a combination saw or drop saw or a docking saw provided that a fine tooth finishing blade is used. In this operation the Tripstop must always be laying flat and firmly against the fence of the saw. The underside of the profile facing the fence must be supported to the extent that the bottom edge facing the operator sits firmly on the table of the saw. The whole profile must be below the top of the fence at all times.



Caution. Tripstop must never be cut with a chain saw, a hand held portable power saw or with a blade used for ripping. If in doubt use hand operated saws. Full personal protective equipment must be worn including leather gloves, eye and hearing protective gear. A full face mask is preferable to goggles. Pieces of Tripstop less than 100 mm or 4" must never be cut using power equipment.